DMV Lane Technician Observation Report

OMV Technician: Pavin Bernes Position: 1 or 2				
Station: Wilming Ton Date: 11-13-2014 Time: 12 17				
Vehicle Make: Merz Model E 35	0	Year	20	11
GVWR: Fuel Type: 6 A 5 Registration Number: VIV 33 5				
Auditor: Coverdole - Covert/Overt (Circle One)				
		YES	NO	N/A
1. Did technician check vehicle paper work and verify VIN number?		6		
2. Was Emissions testing required?		6		
a) Was Emissions testing performed using OBD?		1		
b) Was Emissions testing performed using Analyzer Probe?				
c) Was Emissions testing performed using Paddle(s)?			D	
d) Was Emissions testing performed using Clip?				
3. Was Catalytic Converter inspection required?				4
a) Was Catalytic Converter inspection performed?				
4. Was Fuel Tank pressure testing required?				6
a) Was Fuel Tank pressure testing performed?				
5. Was Fuel Cap pressure testing required?				
a) Was Fuel Cap pressure testing performed?				
6. Is this test a Re-check from a prior failure?				
a) Which re-check test is being performed? 1 2 3 (cir	cle one)			
b) If this is re-check #3, was repair paperwork verified for waiver?				
Sussex County Only				
7. Was Curb Idle testing required?				
a) Was Curb Idle testing performed?				
Comment: 100H F8 H B4GA3	11939			
Technism Had Driver STERT ann 1	OT TEGI	mioza	D	10)
NOT Chuak mil				

Original 08/06/2009/TMP